

## How Would You Cope?

In January Court Bulletins, a [Supervisor](#) and a [Forman](#) were separately charged for two different accidents and found guilty under the Occupational Health and Safety Act which resulted in guilty plea's and fines. One was as a result of a fatality and the other was due to a critical injury or a fellow worker.


Nobody goes to work to get injured. And we all truly believe that “it won’t happen me”. But it does. It is not just employers or corporations who can be charged and have to live with this. It could be you, the supervisor, the lead hand, the Forman: anyone who has charge of a workplace or control over a worker.

The question, “how would you cope?” was not asking you if you could afford the fine or if your reputation could survive the guilty charge.

The question is asking how would you cope with knowing, if you had done something differently, you could have prevented the injury or death of a fellow worker.

Competent Supervisor training is to protect supervisors, protect workers and to protect the employer. Do you, as a supervisor, have enough training? Do you need more training to adequately protect workers?

Contact us at [info@safetyscope](mailto:info@safetyscope) if we could help or click on the [info sheet](#) for more information.



**SAFETY SERVICES**

### Competent Supervisor Health & Safety and the Law

Ontario's Occupational Health and Safety Act states employers must appoint competent supervisors. Whether you are newly appointed or someone who has been in the role for sometime, this workshop will bring you up to date with the legal requirements and concepts related to the Act. Specifically, the workshop provides participants with the skills and knowledge required to manage and implement health and safety in their respective roles.

On completion you will:

- Understand the roles and responsibilities of all workplace parties
- Gain a working knowledge of the Occupational Health and Safety Act and Regulations that apply to your workplace
- Be aware of recent changes in the Occupational Health and Safety Act and Regulations
- Capable of identifying potential hazards to employees in the workplace
- Realize that contributing factors can increase the risk of potential workplace hazards and understand the fundamentals of accident prevention
- Identify with and support the concept of Due Diligence
- Familiar with your legal responsibilities with regards to work refusals, injury reporting and critical injuries
- Be prepared and know what to do if the Ministry of Labour, Immigration, Training & Skills Development arrives at your workplace

Who should attend this 1 day workshop?

- Supervisors / Lead Hands
- Managers
- Owners

On successfully passing the final evaluations the learner will receive a certificate of completion

**Safety Services**

- Traffic Control Person
- Traffic Control Program
- JHSC Certification Training
- Workplace Inspection / Accident Investigation
- Competent Supervisor
- Lockout / Tagout Energy Hazards
- Confined Space Attendant, Entry and Rescue

2501 Rutherford Road Unit 22  
Vaughan, Ontario L4K 2N6  
Phone: 416-231-3752  
E-mail: [info@safetyscope.net](mailto:info@safetyscope.net)  
Version: 1.0/24

## Court Bulletins Fatalities

**Review the bulletin below and click on the link to learn more if this hazard could occur in your workplace.**



### [Jan 23 Fatality—Alfredo Piluso, the Forman of Road-Ex Contracting Ltd., Fined \\$20,000](#)

Road-Ex and a subcontractor were constructing a new driveway as part of a commercial building project. Mr. Piluso was supervising the workers and acting as the signaller for the rock truck operated by a worker employed by the subcontractor. He signalled the operator to haul the load and then turned away from signalling the rock truck to take measurements of the soil grade where the excavator was actively digging. The operator of the rock truck did not see a worker standing in the intended path of travel due to an obstructed view.

By performing other work while acting as a signaller, Mr. Piluso failed, as a worker, to work in compliance with S 104(3) and 106(1) of Reg. 213/91, contrary to section 28(1)(a) of OHSA.

### [Jan 22 Excavation Fatalities and Critical Injuries - Direct Underground Inc. Fined \\$250,000](#)

Four workers were injured, two of them fatally, during the installation of a new underground sewer system a wall of the excavation collapsed.

The investigation found that the excavation wall had a weaker layer of soil present, which was classified as Type 3 per Reg. 213/91. This required shoring or appropriate sloping of the walls to prevent unstable conditions leading to collapse. The investigation also found that there was no engineering opinion on the stability of the excavation wall, and no support system installed for the weaker layer of soil.

The employer failed ensure that the walls of the excavation were supported by a shoring system or appropriately sloped, as required by S 234(1) of Reg. 213/91, contrary to S 25(1)(c) of the OHSA.

## New Format for Safetyscope News

As we have kept you up to date, the rebranding of Natt Safety Services continues. This will be your final issue of “Safetyline”, you will now receive news through Natt Group marketing department in a different look and feel.

Keep your eyes out to ensure it is not captured in your spam.

## Questions? Comments?

Natt Safety Services wants to hear from you.






If you want to ask questions about our training sessions, safety consulting, etc.

[Please contact us.](#)

**Questions? Comments?**  
**We want to hear from you.**

If you want to ask questions about our training sessions, safety consulting, etc. please contact us.

Choose from one of our locations below:

Lively	Brockville	Sault Ste. Marie	Timmins	Vaughan
				
98 Fielding Road Lively, ON 1 866 244 3334	Unit 1, 3524 Coons Rd. Brockville, ON 1 888 294 1943	117 White Oak Drive East, Sault Ste. Marie, ON 249 889 6160	1052 Riverside Drive Timmins, ON 1 866 244 3334	2501 Rutherford Road Vaughan, ON 1 866 244 3334

## Court Bulletins Critical Injuries

Review the bulletin below and click on the link to learn more if this hazard could occur in your workplace.



### [Jan 28 Critical Injury - Canadian General - Tower Limited Fined \\$175,000](#)

Workers at an emboss station, where layers of material are combined and embossed onto rolls, noticed a defect mark on the finished product.

A worker entered the emboss station, while the machine was still running, to examine the roller surfaces inside the machine and their gloved hand was caught between two counter-rotating rollers. These created a pinch point that critically injured the worker.

The employer failed to ensure the worker was protected from the pinch point, as required by S 25 of Reg. 851/90, contrary to S 25(1)(c) of the OHSA.

### [Jan 27 Ryan Wilkes, Project Supervisor, The Lake Partnership fined \\$10,000](#)

Mr. Wilkes was the project supervisor at the site, which included workers from Mr. Wilkes' company and two framing subcontractors. There were openings in the floor at each level of the building for a planned elevator shaft. The opening to the elevator shaft on the first floor was covered by sheets of insulation made of dense polystyrene, featuring the words "DO NOT STEP."

While a framer was working on the first floor, they stepped onto the material, which did not meet the requirements for a protective covering, covering the opening for the elevator shaft and fell through to the basement floor.

Mr. Wilkes failed, as a supervisor, to ensure that the worker was protected by a guardrail or protective covering as required by S 26.3(2) of Reg. 213/91, contrary to S 27(1)(a) of the OHSA.

### [Jan 24 Lack of Guarding Critical Injury - Cerelia Bakery Canada Fined \\$85,000](#)

A worker, employed by a temporary help agency, was working on the cookie producing line at one of three oven conveyors in operation at the facility.

To rest after prolonged standing, the worker sat on a guardrail parallel to the conveyor. The worker rested one foot on a step platform outside the guardrail and moved their other leg through a 16-inch space between the guardrail and the conveyor to rest their foot on the lower frame of the conveyor. While in this position, the worker lost balance and was injured by a pinch point on the conveyor.

An inspection found that there was no adequate guarding to prevent access to the pinch point from above.

The employer, failed to ensure that the conveyor was guarded to prevent access to the pinch point, as required by S 25 of Reg. 851/90, contrary to S 25(1)(c) of the OHSA.

## NATT Safety Services Other Upcoming Courses

### 98 Fielding Road, Lively

#### Working at Heights

- Mar 3 @ 8:00 am - 4:30 pm
- Mar 10 @ 8:00 am - 4:30 pm
- Mar 17 @ 8:00 am - 4:30 pm
- Mar 24 @ 8:00 am - 4:30 pm
- Mar 31 @ 8:00 am - 4:30 pm

#### Working at Heights Refresher

- Mar 5 @ 8:00 am - 12:00 pm
- Mar 12 @ 8:00 am - 12:00 pm
- Mar 19 @ 8:00 am - 12:00 pm
- Mar 26 @ 8:00 am - 12:00 pm

### 117 White Oak Dr. E Sault Ste. Marie

#### Working at Heights

Mar 19 @ 8:00 am - 4:30 pm

#### Working at Heights Refresher

Mar 19 @ 12:00 pm - 4:30 pm

#### Overhead Crane Operator Training

- Mar 25 @ 8:00 am - 4:30 pm

#### Mobile Elevated Work Platform

- Mar 11 @ 8:00 am - 4:30 pm
- Mar 27 @ 8:00 am - 4:30 pm

#### Basic Rigging Fundamentals

- Mar 20 @ 8:00 am - 4:30 pm



## NATT Safety Services provides Safety Training and Industrial Services.

Our training includes CPO-Approved Working at Heights, Confined Space, Power Elevated Work Platform, Forklift, Indoor Fire Extinguisher Simulator training, and much more. We also have several online training courses available. Contact us for a custom quote.

For more information about our training and services, [contact us today!](#) To Register access [Click Here](#)

If you are a manager, director, leader or business owner and you find yourself giving warnings instead of enforcing your organizations rules find out where your potential liabilities are.

### GEOARC Level 1 Rope Access Training

NATT & Safetyscope partnered with GEOARC at their Burlington Training Centre. Staff attending on Nov 18th completed the Level 1 Technician Rope Access Training including a rope rescue component.


We look forward to working closely with the GEOARC team for future training and rope access work.



## Joint Health and Safety Training (In Class and Distance Learning)

Safetyscope can help with:

- In Class sessions for DBC Inc. JHSC Part 1 and JHSC Part 2
- Distance Learning (Virtual) Refresher training utilizing DBC Inc. approved training
- In Class sessions for Safetyscope JHSC Refresher Training



## Safetyscope is an approved provider of the MLITSD

We have continued to expand our scope and now Safetyscope is an approved provider for the following:

- Safetyscope is an approved provider for JHSC Refresher Training
- Safetyscope is an approved provider for Working @ Heights Training
- Safetyscope is an approved provider for W@H Refresher Training
- Toronto Water Approved Provider for Working at Heights
- TSSA Approved Training Provider
- Corrections Canada Approved provider for



## NATT Safety Services Public Training Locations

[2501 Rutherford Road Unit 22](#) Vaughan, ON 416.231.3752

[98 Fielding Road Lively, ON](#) Toll Free 1.866.244.3334

Unit 1, 3524 Coons Rd. Brockville, ON 1.888.294.1943

117 White Oak Drive East, Sault Ste. Marie, ON 249.889.6160



## Safetyscope Continuing to Maintaining Registration as an OWWCO Training Provider

These courses meet the criteria in subsection 29(4) of O.Reg. 128, Certification of Drinking Water System Operators and Water Quality Analysts. On Completion of training all participants will receive a certificate of completion with corresponding CEU Value.

1. Working at Heights	.7 CEU
2. WHMIS	.4 CEU
3. TDG	.4 CEU
4. Working in Confined Spaces Rescue Level	2.8 CEU
5. Confined Spaces Attendant Non Entry	1.3 CEU
6. Confined Spaces Advanced Entrant	.7 CEU
7. Confined Spaces Attendant Refresher	.7 CEU
8. Confined Spaces Rescue Refresher	.7 CEU
9. Standard First Aid	1.4 CEU
10. Self Contained Breathing Apparatus	.4 CEU
11. Spill Response	.7 CEU
12. Trenching Hazards	.4 CEU



# Natt Safety Services / Safetyscope



2025 SCHEDULE

**First Day Attendant Course**  
**Time:** 8:00 am – 4:00 pm  
**Second Day ½ day Entrance Course**  
**Time:** 8:00 am – 12:00 pm

January	21 - 22
February	18 - 19
March	18 - 19
April	15 - 16
May	13 - 14
June	17 - 18
July	15 - 16
August	12 - 13
September	16 - 17
October	14 - 15
November	18 - 19
December	16 - 17



**Competent Supervisor**  
**1 Day Course**  
**Time:** 8:00 am – 4:00 pm

February	26
April	24
June	26
August	28
October	23





**Day 1 - Emergency Level/Recertification**  
**Day 2 - Standard First Aid Level C**  
**Time:** 8:00 am – 4:00 pm

February	3 - 4
May	5 - 6
August	5 - 6
November	4 - 5




**Working At Heights**  
**1 Day Course**  
**Time:** 8:00 am – 4:00 pm

January	17 & 31
February	14 & 28
March	14 & 28
April	11
May	2, 16 & 30
June	13 & 27
July	11 & 25
August	8 & 22
September	5 & 19
October	3, 17 & 31
November	14 & 28
December	12

**Working At Heights Refresher**  
**1/2 Day Course**  
**Time:** 8:00 am – 12:00 pm

January	10 & 24
February	7 & 21
March	7 & 21
April	4 & 25
May	9 & 23
June	6 & 20
July	4 & 18
August	1, 15 & 29
September	12 & 26
October	10 & 24
November	7 & 21
December	5 & 19



**JHSC Part 1 Certification**  
**Dwight Barratt Inc. - 3 Day Course**  
**Time:** 8:00 am – 4:00 pm

March	24 - 26
August	18 - 20
November	24 - 26

**Part 2 and Refresher also available**



**Confined Space Rescue**  
**4 Day Course**  
**Time:** 8:00 am – 4:00 pm

May	26 - 29
December	8 - 11




Course held at the Safetyscope Training Centre  
 2501 Rutherford Road Unit 22 Vaughan, Ontario L4K 2N6  
 Phone: 416.231.3752 E-mail: info@safetyscope.net